

Labor and Materials

Copper } Connection.....	\$
Lead }	\$
Curb } Cock Valve }	in.....
} T. S. & V. }	\$
Service Box } Short 3 1/2 x 4 1/2 }	\$
Old returned } Long 4 1/2 x 5 1/2 }	\$
} Buff. or Rdway }	\$
Pt.....in. } Copper } Pipe at.....	\$
} Galv. Iron }	\$
} Cast Iron }	\$
Nipples.....in. at.....	\$
Bushings.....to.....in. at.....	\$
Red'g } Couplings.....to.....in. at.....	\$
Inc'g }	\$
Union.....in. at.....	\$
Meter.....in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick } Mack } at.....	\$
} Red }	\$
} Asphalt }	\$
Lead Joints at.....	\$
Leadite Joints at.....	\$
Hrs. Foreman at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$
Trucking.....	\$
Builders' Use of Water.....	\$
Total \$.....	

226
Labor and Material Report June 22 1931

1931

Vacant lot 176 Ridge St

This measurement
is from 178 Ridge St
for 176-226
a vacant
lot,



Main

Elev of Main at tap

Gate at

TAX ID#

302.12-27-2

Gate at

● Curb Box

This Tap for ~~176~~
Ridge St 226

~~No Tap made.~~

Vacant Lot
Measured from
228 Ridge St.