

LABOR AND MATERIALS

1	Copper	} Connection	1"	\$	_____
1	Lead				\$
1	Curb	} Cock Valve T.S. & V.	1 in.	\$	_____
1	Service box		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway.		\$
	Old returned				\$
15	Ft. 1 in.	} Copper C.I. C.I.	Pipe at	\$	_____
					\$
	Nipples	in. at		\$	_____
	Bushings	to in. at		\$	_____
	Red'g Inc'g	} Coupl'gs	to in. at	\$	_____
	Union		in. at		\$
	Meter	in. at		\$	_____
	Lead Joints at			\$	_____
	Compound Joints at			\$	_____
	Maintenance Foreman			\$	_____
	Hrs. Water Maint. Man-1	at		\$	_____
	Hrs. Water Maint. Man-2	at		\$	_____
	Hrs. Garage Foreman	at		\$	_____
	Hrs. Labor-	at		\$	_____
	Hrs. Compressor at			\$	_____
	Compensation Ins. at \$	per C		\$	_____
	Trucking			\$	_____
	Pav't Patch			\$	_____
	Tap by GLEBOUR			\$	_____
	1/2 Cd. 8-3-61.			\$	_____
	O'head			\$	_____
				\$	_____

1

North End.

Roosevelt ~~St.~~  
~~Pl.~~  
Ave. No. \_\_\_\_\_

Name of Owner Tap for  
1" Copper Main

Labor and Mat'l. Report Aug 3 19 61.



16" Main Elev. of Main at tap 4'

Gate at • Gate at

15' copper

• Curb Box

This Tap Feeds  
23 + 25 Roosevelt  
are.  
Runs Between Curb  
& Side Walk.

LSM-50-3-10-61