

## LABOR AND MATERIALS

1 - <del>Lead</del>	Copper Connection	3		\$ 1.31
1 - Curb	Cock Valve T. S. & V.	3	in.	\$ 1.75
1 - Service Box Oid returned	} Short 3/2x4 1/2 Long 4/2x5 1/2 Buff. or Rdway	}		\$ 1.60
36 Ft.	3/4 in.		Pipe at	18 \$ 6.48
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
2	Hrs. Chauffeur	at 6 1/2		\$ 1.75
4	Hrs. Tapper	at		\$ 2.50
4	Hrs. Labor	at 4 1/2		\$ 1.80
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 17
	Trucking			\$ 1 -
	Builders Use of Water	1/2 Patch (sewer)		\$ 2.50
	Tracy by Hassel			\$
				\$
				\$
				\$
				\$
				\$ 20.36

11 - 1940

St.

Pt.

Ave. No. 3

Name of Owner

A.F. Broughton

Labor and Mat'l. Report

Sept 16 1940

Roosevelt Ave



Coolidge Ave.

6 Main

Elev. of Main at tap 5

Gate at ●

● Gate at

36' to main

3/4"

● Curb Box

TAX ID# 302.15-10-8