

LABOR AND MATERIALS

1	Copper Lead	{ Connection	$\frac{3}{4}$		\$ 1.23
1	Curb	{ Cock Valve T-S. & V.	$\frac{3}{4}$	in.	\$ 1.68
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway			\$ 1.54
10	Ft. $\frac{3}{4}$ in.	{ Copper Galv. Iron Cast Iron		Pipe at 17	\$ 1.70
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
3	Hrs. Chauffeur	at	.62 1/2		\$ 1.88
2	Hrs. Tapper	at			\$ 1.25
3	Hrs. Labor	at	.45		\$ 1.35
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$
	Trucking				\$ 1.14
	Builders Use of Water				\$
	Taphy Hassel				\$
	Patch - 1/2 Sewer Dept.				\$ 2.50
					\$
					\$ 14.27

34 -- 1939

St.

Pl.

Roosevelt + Pershing Ave. No. 18

Name of Owner

Willmott

Labor and Mat'l. Report

June 28 1939



6 Main Pershing Elev. of Main at tap 4
Gate at ● Road Gate at ●

TAX ID # 302.14-1-50

● Curb Box

3/4" - 10' COPPER

New York