

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4		\$ 1.31
1	Curb	{ Cock Valve T-S. & V. }	3/4	in.	\$ 1.75
1	Service Box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway }			\$ 1.60
12	Ft.	3/4	in.	{ Copper Galv Iron Cast Iron }	Pipe at 18 \$ 2.16
	Nipples	in.	at		\$
	Bushings	to	in.	at	\$
	Red'g Inc'g	{ Couplings	to	in.	at \$
	Union	in.	at		\$
	Meter	in.	at		\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
4	Hrs. Chauffeur	at	6 1/2		\$ 2.50
8	Hrs. Tapper	at	"		\$ 5.00
11	Hrs. Labor	at	45		\$ 4.95
	Hrs. Labor	at			\$
1	Hrs. Compressor	at	6 1/2		\$
	Compensation Ins.				\$ 38
	Trucking				\$ 1-
	Builders Use of Water	Patch			\$ 5.00
	Tap by Hessel				\$
					\$
					\$
					\$
					\$
					\$ 25.65

7 - - - 19

St. **19**
Pt. **13**
Ave. No. **13**

Name of Owner
Conway

Labor and Mat'l. Report Dec 23 1939

4 Main Elev. of Main at tap 5

Gate at ● Gate at ●

TAX ID # 303.139-17

● Curb Box

12' to MAIN
3/4" COPPER

old Tap set off