

LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/4"	\$
1	Curb	Cock Valve T.S. & V.	1 1/4 in.	\$
2	Service box	Short 3 1/2 x 4 1/2	} \$	Small
	Old returned	Long 4 1/2 x 5 1/2		
		Buff or Rdway		
36	Ft. 1 1/4 in.	Copper C.I. C.I.	Pipe at	\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man	1 at		\$
	Hrs. Water Maint. Man	2 at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Giesbard & Co.			\$
	8-16-61.			\$
	O'head			\$

Cornor Hunter of
 Sagamore
 Sts Pl. Ave. No.
 Name of Owner
 City Pipe
 Labor and Mat'l. Report AUG 16 1960
 Sagamore St. 2 1/8" mueller Hyd.
 Curb box
 3/4" stop
 For Field House
 Curb Box 1 1/4" stop.
 4" CH. Main Elev. of Main at tap 4'
 Gate at TAX ID # Gate at
 303.13-8-9
 Field House
 Curb Box
 N. New Field House
 S. 1966
 LSM-5C-3-10-61