

Labor and Materials

1	Copper	Connection	3/4"	\$	3.20
	Lead				
1	Curb	Cock Valve T-S. & V.	3/4" in.	\$	1.00
2/20	Service Box	Short 3 1/2 x 4 1/2		\$	
	Old returned	Long 4 1/2 x 5 1/2		\$	
		Buff. or Rdway		\$	
5	Ft.	3/4" in. Copper Galv. Iron Cast Iron	Pipe at	\$	1.76
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack Red Asphalt	at	\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
2	Hrs. Foreman	at		\$	1.25
2	Hrs. Common Labor	at		\$	62
2	Hrs. Common Labor	at	40 1/2	\$	41
	Hrs. Mason	at		\$	
	Hrs. Mason's Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins.			\$.06
	Trucking			\$	1.50
	Builders' Use of Water			\$	
				\$	<u>9.33</u>
Total \$					

27-128 33-A-B
Labor and Material Report July 29 1927

W. City at 20 Sacramento



6" Main Elev. of Main at tap 4"
 Gate at ● Gate at ●

● Curb Box

TAX ID # 303.13-3-15

8' to MAIN
 3/4" COPPER