LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection 3/4	$ 1.31
1	Curb { Cock / ~~Valve~~ / ~~T. S. & V.~~ } 3/4 in.	$ 1.60
1	Service Box Old returned { ~~Short 3½x4½~~ / ~~Long 4½x5½~~ / ~~Buff. or Rdway~~ } used same	$ —
28	Ft. 3/4 in. { Copper / ~~Galv Iron~~ / ~~Cast Iron~~ } Pipe at 18	$ 5.04
	Nipples ____ in. at	$
	Bushings ____ to ____ in. at	$
	Red'g / Inc'g Couplings ____ to ____ in. at	$
	Union ____ in. at	$
	Meter ____ in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
4	Hrs. Chauffeur at 62½	$ 2.50
8	Hrs. Tapper at	$ 5.00
8	Hrs. Labor at 45	$ 3.60
	Hrs. Labor at	$
	Hrs. Compressor at	$
	Compensation Ins.	$ .34
	Trucking	$ 1.—
	Builders Use of Water Patch	$ 5.—
	Tap by Hessel	$
		$
		$
		$
		$ 25.39

12 8 - - 1940

St. ~~Ft.~~ 44-H-13

Saggamore Ave. No. 382

Name of Owner

Clarke

Labor and Mat'l. Report May 1 1940

6 Main

Elev. of Main at tap 4'6"

Gate at ● ● Gate at

TAX ID # 303.13-2-4

● Curb Box

28' to main

3/4" copper

JH