

LABOR AND MATERIALS

1	Copper Lead	{ Connection	$\frac{3}{4}$	-----	\$ 1.31
1	Curb	{ Cock Valve T.S. & Y.	$\frac{3}{4}$ in.	-----	\$ 1.75
1	Service Box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff. or Rdway		-----	\$ 1.60
11	Ft. $\frac{3}{4}$ in.	{ Copper Galv. Iron Cast Iron	Pipe at 18	-----	\$ 1.98
	Nipples	in. at		-----	\$
	Bushings	to in. at		-----	\$
	Red'g Inc'g	{ Couplings	to in. at	-----	\$
	Union	in. at		-----	\$
	Meter	in. at		-----	\$
	Lead Joints	at		-----	\$
	Leadite Joints	at		-----	\$
	Hrs. Foreman	at		-----	\$
3	Hrs. Chauffeur	at	62 1/2	-----	\$ 1.88
8	Hrs. Tapper	at	"	-----	\$ 5.00
11	Hrs. Labor	at	45	-----	\$ 4.95
	Hrs. Labor	at		-----	\$
3	Hrs. Compressor	at	62 1/2	-----	\$ 1.87
	Compensation Ins.			-----	\$ 1.36
	Trucking			-----	\$ 1.00
	Builders Use of Water	patch		-----	\$ 5.00
	Tap by Hossell			-----	\$
	Ground frozen 3' Deep			-----	\$
				-----	\$
				-----	\$
				-----	\$ 26.70

9 --- 1

St. **64**
 Pt. **64**
 Ave. No. **64**

Sagamore St

Name of Owner
 F. K. White

Labor and Mat'l. Report **Feb 23** 19 **20**

6 Main Elev. of Main at tap **3 1/2**

Gate at ● Gate at ●

TAX ID # 303.9-10-1

● Curb Box

11' to main
 3/4" copper

New House