

### Labor and Materials

1	Copper } Connection.....	\$ 320
	Lead } .....	
1	Curb } Cock } 3/4 in.....	\$ 100
	} Valve } .....	
	} T. S. & V. } .....	
1	Service Box } Short 3 1/2 x 4 1/2 } .....	\$ 130
	Old returned } Long 4 1/2 x 5 1/2 } .....	
	} Buff. or Rdway } .....	
1.8	Ft. 3/4 in. } Copper } Pipe at.....	\$ 396
	} Galv. Iron } .....	
	} Cast Iron } .....	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g } .....	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick } Mack } at.....	\$
	} Red } .....	
	} Asphalt } .....	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
2	Hrs. Foreman at... 50	\$ 100
	Hrs. Common Labor at.....	\$
1.2	Hrs. Common Labor at... 4.057	\$ 4.87
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 17
	Trucking.....	\$ 100
	Builders' Use of Water.....	\$
Total		\$ 16.50

26-37

69

Labor and Material Report

June 11

1926

59 Sagamore St

# 59

69

27'9"

67-9"

35'-2"

Curb Box

6'

Main

Elev. of

Main at tap

Gate at

TAX ID # 303.9-11-9

Gate at

Curb Box

18' to MAIN

3/4" COPPER