

Labor and Materials

1	Copper	Connection.....	\$ 3.20
	Lead		
1	Curb	{ Cock Valve } T. S. & V. { 3/4 in.....	\$ 10.00
1	Service Box	{ Short 3/4 x 4 1/2 } Old returned { Long 4 1/2 x 5 1/2 } Buff. or Rdway }	\$ 1.30
20	Ft. 3/4 in.	{ Copper } Pipe at.....	\$ 4.40
		{ Galv. Iron }	
		{ Cast Iron }	
	Nipples.....	in. at.....	\$
	Bushings.....	to..... in. at.....	\$
	Red'g Inc'g	{ Couplings..... to..... in. at.....	\$
	Union.....	in. at.....	\$
	Meter.....	in. at.....	\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement at.....		\$
	Paving Brick	{ Mack } Red } at.....	\$
		{ Asphalt }	
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
	Hrs. Foreman at.....		\$
2	Hrs. Common Labor at.....	5.0	\$ 1.00
1.2	Hrs. Common Labor at.....	4.07	\$ 4.87
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
	Hrs. Compressor at.....		\$
	Compensation Ins.....		\$ 1.7
	Trucking.....		\$ 1.00
	Builders' Use of Water.....		\$
Total			\$ 16.94

26-35 73

Labor and Material Report June 11 1926

63 Sagamore St 3/4" Tap

6" Main Elev. of Main at tap

Gate at ● Gate at ●

TAX ID # 303.9-11-7

● Curb Box

20' to MAIN
3/4" COPPER