

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$	
1	Lead	Cock		\$	
1	Curb	Valve	3/4" in.	\$	
		T.S. & V.		\$	
1	Service box	Short 3 1/2 x 4 1/2		\$	
	Old returned	Long 4 1/2 x 5 1/2		\$	
		Buff or Rdway		\$	
9	Ft. 3/4 in.	Copper	Pipe at	\$	
		G.I.		\$	
		G.I.		\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g			\$	
	Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1 at			\$	
	Hrs. Water Maint. Man-2 at			\$	
	Hrs. Garage Foreman at			\$	
	Hrs. Labor at			\$	
	Hrs. Compressor at			\$	
	Compensation Ins. at \$	per C		\$	
	Trucking			\$	
	Pav't Patch			\$	
	Tap by Giggord & Miller + Co.			\$	
	6-22-60.			\$	
	O'head			\$	
				\$	

St. 194
-Pl. 792
Ave. No. 792

Name of Owner
Andrew J. Capezzuti

Labor and Mat'l. Report June 22 1960

Garage
43'
57' 3"
Curb Box

12" Main Elev. of Main at tap 3 1/2'

Gate at • Gate at

• Curb Box

This TAP ON Side
of MAIN.
9' to main
3/4" COPPER

LSM-BC-2-5 56