

LABOR AND MATERIALS

Copper	} Connection		\$
Lead			
Curb	} Cock Valve T. S. & V.	in.	\$
Service box	} Short 3½ x 4½ Long 4½ x 5½		\$
Old returned			
Ft. ^{3/4} in.	} Copper C.I. C.I.	Pipe at	\$
Nipples	in. at		\$
Bushings	to in. at		\$
Red'g } Inc'g }	Coupl'gs	to in. at	\$
Union	in. at		\$
Meter	in. at		\$
			\$
Compound Joints	at		\$
Maintenance Foreman			\$
Hrs. Water Maint. Man-1	at		\$
Hrs. Water Maint. Man-2	at		\$
Hrs. Garage Foreman	at		\$
Hrs. Labor	at		\$
Hrs. Compressor	at		\$
			\$
Trucking			\$
Pav't Patch			\$
			\$
			\$
			\$
			\$

St.
~~Pl.~~
Ave. No. 210

SANFORD

Name of Owner
E. RUSU

Labor and Mat'l. Report 19 90

LOT TAP

● Curb Box

Main	Elev. of Main at tap
Gate at ●	● Gate at

TAX ID # 303.9-7-38

● Curb Box

3/4" COPPER