

LABOR AND MATERIALS

/ Copper Lead	} Connection	3/4	\$	2.90
/ Curb	{ Clock Valve T. S. & V. }	3/4 in.	\$	3.60
Service box Old returned	{ Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway }		\$	—
21 Ft.	3/4 in.	{ Copper Galv. Iron Cast Iron }	Pipe at	35 7.35
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g Inc'g	{ Couplings	to in. at	\$	
Union	in. at		\$	
Meter	in. at		\$	
Lead Joints at			\$	
Compound Joints at			\$	
3 Hrs. Foreman at	W.W.M.	9 1/2 hr	\$	2.78
7 Hrs. Chauffeur at		8 1/2 hr	\$	5.77
Hrs. Tapper at			\$	
11 Hrs. Labor at		7 1/2 hr	\$	7.89
Hrs. Labor at			\$	
Hrs. Compressor at			\$	
Compensation Ins.	2.207		\$	3.6
Trucking			\$	1.30
Builders Use of Water			\$	5.30
Tepaly Warsawski				
				\$36.83

2-47

St. Sanford
Pt. Ave. No. 35

Name of Owner
Mrs Farrar

Labor and Mat'l. Report Feb 26 1947

● Curb Box

6 Main Elev. of Main at tap 5 1/2

Gate at ● ● Gate at

TAX ID # 302.16-11-12

● Curb Box

21' to main
3/4" copper
Pulled ✓
to be changed

LSM-5C-6-1-45