

LABOR AND MATERIALS

1	Copper	{	Connection	3/4"	\$	2.79
	Lead	}				
1	Curb	{	Cock Valve	3/4" in.	\$	2.70
		}	T. S. & V.			
1	Service box	{	Short 3 1/2 x 4 1/2		\$	4.25
	Old returned	}	Long 4 1/2 x 5 1/2			
			Buff or Rdway			
11	Ft.	{	Copper	Pipe at 35	\$	3.85
		}	G.I.			
			G.I.			
	Nipples		in. at		\$	
	Bushings		to in. at		\$	
	Red'g	{	Coupl'gs	to in. at	\$	
	Inc'g	}				
	Union		in. at		\$	
	Meter		in. at		\$	
	Lead Joints at				\$	
	Compound Joints at				\$	
3	Hrs. Water Maint. Man-1		at	1.17	\$	3.36
2	Hrs. Water Maint. Man-2		at	1.02	\$	2.04
9	Hrs. Labor		at	91	\$	819
	Hrs. Labor		at		\$	
2	Hrs. Compressor at			1.20	\$	2.40
	Compensation Ins. at		\$226 per C.		\$	30
	Trucking				\$	1.00
	Pav't Patch				\$	11.20
	Tap by Miller				\$	
	O'head				\$	
					\$	41.58

St. Sanford
Pl. 38
Ave. No. 38

Name of Owner Allen

Labor and Mat'l. Report Sept 25 1950

#38

33'2"

31'-7"

● Curb Box

6" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID # 302.16-5-32

● Curb Box

11' to main

3/4" copper

LSM-5C 10-21-49