

Labor and Materials

1	Copper	Connection	3	\$ 1.48
1	Curb	Cock	1	\$ 1.79
		Valve		
		T.S.&V.		
1	Service Box	Short 2 1/2 x 4 1/2	1	\$ 1.30
	Old returned	Long 4 1/2 x 5 1/2		
		Butt or Raway		
4	Ft.	Copper	1	\$ 1.80
		Galv. Iron		
		Cast Iron		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	Couplings	to in. at	\$
	Inc'g			\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack	at	\$
		Red		
		Asphalt		
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at		\$ 1.88
8	Hrs. Common Labor	at		\$ 2.60
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins			\$ 1.17
	Trucking			\$ 1.00
	Builders Use of Water	Patch		\$ 5.00
Total				\$ 18.02

Labor and Material Report

Aug 6 1932

5610 Sanford St



4 Main Elev. of Main at tap 6
 Gate at TAX ID # 302.16-7-12 Gate at

Curb Box

old Tap shut off at
 Main
 10' to MAIN
 3/4" COPPER
 G.K. [Signature]