

### Labor and Materials

Copper } Connection.....	3	\$ 2.70
Lead } .....		
Curb { Cock	3	\$ 2.31
{ Valve		
{ T. S. & V. } .....		
Service Box { Short 3/4x4 1/2	1	\$ 1.45
Old returned { Long 1 1/2x5 1/2		
{ Buff. or Rdway } .....		
9 Ft. .... in. { Copper	3	\$ 2.43
{ Galv. Iron } Pipe at.....		
{ Cast Iron } .....		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g } .....		\$
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick { Mack	1	\$
{ Red		
{ Asphalt } at.....		
Lead Joints at.....		\$
Leadite Joints at.....		\$
3 Hrs. Foreman at.....		\$ 1.88
14 Hrs. Common Labor at.....		\$ 6.30
Hrs. Common Labor at.....		\$
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 20
Trucking.....		\$ 1
Builders' Use of Water Patch.....		\$ 5
Total \$		23.40

30-107  
Labor and Material Report

Aug. 18 1930

574 Standard St.



6 Main Elev of Main at tap 7

Gate at TAX ID # 302.16-7-13 Gate at

Curb Box

*Old tap disconnected.*

9' to main  
3/4" copper