

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.29
1	Curb	Cock Valve T-S. & V.	3/4" in.	\$	2.70
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	4.25
9	Ft. 3/4 in.	Copper G.I. G.I.	Pipe at 35	\$	3.15
	Nipples	in. at		\$	
1	Bushings	3/4 to 1/2 in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	1.54
	Hrs. Water Maint. Man-1 at			\$	
4	Hrs. Water Maint. Man-2 at	1.07		\$	4.08
16	Hrs. Labor— at	91		\$	14.56
	Hrs. Labor— at			\$	
2	Hrs. Compressor at	1.20		\$	2.40
	Compensation Ins. at \$	per C.		\$	41
	Trucking			\$	1.00
	Pay't Patch			\$	5.40
	Tap by Marzinski			\$	
	O'head			\$	
				\$	40.24

(Renewal)
11.5-100

St. Sanford
Pt. 82
Ave. No. 82

Name of Owner Warren Jensen.

Labor and Mat'l. Report Aug 25 1950

#82

25' 5" 24' 2"

● Curb Box

6" Main Elev. of Main at tap 5"

Gate at ● Gate at

TAX ID# 302.16-8-6

● Curb Box

9' to MAIN
3/4" COPPER

LSM-SC 10-21-49