

### Labor and Materials

Copper } Connection.....	\$.
Lead } .....	\$.
Curb { Cock } .....	in. .... \$.
{ Valve } .....	in. .... \$.
{ T. S. & V. } .....	in. .... \$.
Service Box { Short 3 1/2 x 4 1/2 } .....	\$.
Old returned { Long 4 1/2 x 5 1/2 } .....	\$.
{ Buff. or Rdway } .....	\$.
30 Ft. 3/4 in. { Copper } Pipe at.....	\$.
{ Galv. Iron } .....	\$.
{ Cast Iron } .....	\$.
Nipples..... in. at.....	\$.
Bushings..... to..... in. at.....	\$.
Red'g } Couplings..... to..... in. at.....	\$.
Inc'g } .....	\$.
Union..... in. at.....	\$.
Meter..... in. at.....	\$.
Lbs. Br. Stone at.....	\$.
Lbs. Sand at.....	\$.
Bags Cement at.....	\$.
Paving Brick { Mack } at.....	\$.
{ Red } .....	\$.
{ Asphalt } .....	\$.
Lead Joints at.....	\$.
Leadite Joints at.....	\$.
Hrs. Foreman at.....	\$.
Hrs. Common Labor at.....	\$.
Hrs. Common Labor at.....	\$.
Hrs. Mason at.....	\$.
Hrs. Mason's Helper at.....	\$.
Hrs. Compressor at.....	\$.
Compensation Ins.....	\$.
Trucking.....	\$.
Builders' Use of Water.....	\$.
Total \$.....	

Labor and Material Report

Apr 21

1926

63 Sanford St.



Main

Elev. of  
Main at tap

Gate at

TAX ID # 302.16-13-18

Gate at

● Curb Box

RENEWAL TAP 1995

30' to MAIN

3/4" COPPER