

Labor and Materials

1	Copper	Connection	3	\$ 3.20
1	Curb	Cock Valve T. S. & V.	3	\$ 1.00
1	Service Box	Short 3" x 4"		
	Old returned	Long 4 1/2" x 5"		
		Buff. or Rdway		\$ 1.40
9	Ft.	Copper Galv. Iron Cast Iron	3/4"	\$ 1.98
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
3	Hrs. Foreman	at	6 1/2	\$ 1.88
17	Hrs. Common Labor	at	40 1/2	\$ 4.88
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Mason's Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$ 18
	Trucking			\$ 1.00
	Builders' Use of Water			\$
Total \$				15.52

28-60
Labor and Material Report

June 18 19 20



6 Main

Elev. of Main at tap 5

Gate at

TAX ID # 302.16-8-8

Gate at

Curb Box

Ad Tap DISCONNECTED

9' to MAIN
3/4" COPPER