

LABOR AND MATERIALS

1 Copper } Connection ^{3/4"} \$ _____
 Lead }
 1 Curb } Cock } 3/4 in. \$ _____
 } Valve }
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 }
 { Buff or Rdway } \$ _____
 20 Ft. ^{3/4} in. { Copper } Pipe at. \$ _____
 } C.I. }
 } C.I. }
 Nipples in. at \$ _____
 Bushings to in. at \$ _____
 Red'g }
 Inc'g } Coupl'gs. to in. at \$ _____
 Union in. at \$ _____
 Meter in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman at \$ _____
 Hrs. Labor at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
 Tap by Gifford + Co \$ _____
 H-9-59 \$ _____
 O'head \$ _____

Sanford St. ~~PT.~~ Ave. No. 25

Name of Owner _____

Labor and Mat'l. Report April 9 1959

6" Main Elev. of Main at tap 8'

Gate at • Gate at •

TAX ID # 302.16-11-16

• Curb Box

20' to MAIN
 3/4" COPPER

LSM-5C-2-5 56