

Labor and Materials

1	Copper	} Connection	3/4	\$. 1.49
1	Lead				
1	Curb	} Cock Valve T.S.&V.	3/4 in	\$. 1.79
1	Service Box Old returned				
		} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$. 1.46
10	3/4 in. Copper Galv. Iron Cast Iron				
	Nipples	in. at			
	Bushings	to in. at			
	Red'g Inc'g	} Couplings.....to.....in.at	
	Union				
	Meter	in. at			
	Lbs. Br. Stone	at			
	Lbs. Sand	at			
	Bags Cement	at			
	Paving Brick	} Mack Red Asphalt	} at
	Lead Joints				
	Leadite Joints	at			
1	Hrs. Foreman	at			\$. 63
6	Hrs. Common Labor	at			\$. 2.70
	Hrs. Common Labor	at		
	Hrs. Mason	at		
	Hrs. Masons Helper	at		
	Hrs. Compressor	at		
	Compensation Ins				\$. 11
	Trucking			
	Builders Use of Water				\$. 2.50
	Total				\$. 13.47

32-94
 Labor and Material Report Aug 16 1932

114
 70 Sanford St



6 Main

Elev. of Main at tap 51

Gate at ● TAX ID # 302.12-25-1 ● Gate at

● Curb Box

No measurement
 10' to main
 3/4" COPPER

OK