

LABOR AND MATERIALS

| | | | | |
|----|-----------------------------------|---|--|----------|
| 1 | Lead } Connection | 3/4 | | \$ 1.59 |
| 1 | Curb } Cock Valve T. S. & V. } | 3/4 | in. | \$ 2.74 |
| 1 | Service Box Old returned | Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buffer Rdway | | \$ 1.82 |
| 24 | Ft. | 3/4 | in. } Copper Galv Iron Cast Iron } Pipe at | \$ 4.18 |
| 1 | Nipples | 1/2 | in. at | \$ |
| | Bushings | | to in. at | \$ |
| 1 | Red'g Ine'g } Couplings | 1/2 to 3/4 | in. at | \$ |
| | Union | | in. at | \$ |
| | Meter | | in. at | \$ |
| | Lead Joints at | | | \$ |
| | Leadite Joints at | | | \$ |
| | Hrs. Foreman at | | | \$ |
| 10 | Hrs. Chauffeur at | 68 3/4 | | \$ 6.87 |
| 2 | Hrs. Tapper at | 68 3/4 | | \$ 1.38 |
| 8 | Hrs. Labor at | 62 1/2 | | \$ 5.00 |
| 10 | Hrs. Labor at | 60 | | \$ 6.00 |
| | Hrs. Compressor at | | | \$ |
| | Compensation Ins. | | | \$ 59 |
| | Trucking | | | \$ 1.00 |
| | Builders Use of Water | | | \$ 5.00 |
| | Tax on Material | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ 36.17 |

St.
Pl.
Ave. No. 141

Name of Owner
Brown

Labor and Mat'l. Report 9/11/22 1925

6 Main Elev. of Main at tap 6 1/2

Gate at ● ● Gate at

TAX ID # 303.9-12-6

● Curb Box

24' to main
3/4" copper