

LABOR AND MATERIALS

1	Copper	} Connection	$\frac{3}{4}$	in.	\$ 1.23				
	Lead								
1	Curb	} Cock Valve	$\frac{3}{4}$	in.	\$ 1.68				
1	Service Box	} Short $\frac{3}{2} \times \frac{1}{2}$ Long $4 \frac{1}{2} \times 5 \frac{1}{2}$ Buff. or Rdway		in.	\$ 1.54				
	Old returned								
29	Ft. $\frac{3}{4}$ in.					} Copper Galv-iron Cast-iron		Pipe at	\$ 4.08
	Nipples			in. at	\$				
	Bushings			to in. at	\$				
	Red'g Inc'g	} Couplings		to in. at	\$				
	Union			in. at	\$				
	Meter			in. at	\$				
	Lead Joints at				\$				
	Leadite Joints at				\$				
	Hrs. Foreman at				\$				
3	Hrs. Chauffeur at		6 $\frac{2}{3}$		\$ 1.88				
8	Hrs. Tapper at		7		\$ 5-				
8	Hrs. Labor at		45		\$ 3.60				
	Hrs. Labor at				\$				
	Hrs. Compressor at				\$				
	Compensation Ins.				\$ 32				
	Trucking				\$ 1-				
	Builders Use of Water	Patch			\$ 5-				
	<u>Tap by Hessel</u>								
					\$				
					\$				
					\$				
					\$				
					\$ 25.32				

40 - - 1939

St.

Pt.

Sanford

Ave. No. 195

Name of Owner

Fuller

Labor and Mat'l. Report

July 5 - 1939



6 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

TAX ID # 303.9-12-4

● Curb Box

24' to main
3/4" copper

old shut off