

LABOR AND MATERIALS

Copper } Connection	\$
Lead } Connection	\$
Curb { Clock Valve T. S. & V. }	in. \$
Service box } Short 3 1/2 X 4 1/2 Old returned } Long 4 1/2 X 5 3/4 Buff or Rdway }	\$
24 Ft. 3/4 in. } Copper Galv. Iron Cast Iron }	Pipe at \$
Nipples	in. at \$
Bushings	to in. at \$
Red'g } Couplings	to in. at \$
Inc'g } Couplings	to in. at \$
Union	in. at \$
Meter	in. at \$
Lead Joints	at \$
Compound Joints	at \$
Hrs. Foreman	at \$
Hrs. Chauffeur	at \$
Hrs. Tapper	at \$
Hrs. Labor	at \$
Hrs. Labor	at \$
Hrs. Compressor	at \$
Compensation Ins.	\$
Trucking	\$
Builders Use of Water.	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$
	\$

St. _____
 Pl. _____
 Ave. No. 147

Sanford

Name of Owner _____

measured in

Labor and Mat'l. Report Oct 26 1945

Gate at ●

Elev. of Main at tap _____
 Gate at ●

TAX ID # 303.9-12-3

● Curb Box

24' to main
3/4" copper

LSM-5C-6-1-45