

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4	\$
1	Curb			{ Clock Valve T. S. & V. }	1 in.
1	Service box Old returned	} Short 3 1/2 X 4 3/4 Long 4 3/4 X 5 3/4 Buff. or Rdway }		\$
12	Ft.		{ Copper Galv. Iron Cast Iron }	} Pipe at
	Nipples		in. at	
	Bushings		to in. at	\$
	Red'g Inc'g	} Couplings	to in. at	\$
	Union			in. at
	Meter		in. at	\$
	Lead Joints at			\$
	Compound Joints at			\$
	Hrs. Foreman at			\$
	Hrs. Chauffeur at			\$
	Hrs. Tapper at			\$
	Hrs. Labor at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
				\$
				\$
				\$
				\$
				\$
				\$

St. _____
 Pt. _____
 Ave. No. 162

Sanford _____
 Name of Owner _____
 INSTALLED SEPT. 19, 1924

Labor and Mat'l. Report Oct 26 19-25

 162

6" Main Elev. of Main at tap 4 1/2

Gate at ● ● Gate at

TAX ID # 303.9-10-23

● Curb Box

12' to main
 3/4" GAL.

LSM-5C-6-1-45