

LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.27
1	Curb	Cock Valve T.S. & V.	3/4" in.	\$	2.70
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$	4.25
26	Ft. 3/4 in.	Copper G.I. C.I.	Pipe at 35	\$	9.10
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints at			\$	
	Compound Joints at			\$	
4	Hrs. Water Maint. Man-1	at		\$	14.56
16	Hrs. Water Maint. Man-2	at 1.07		\$	4.08
	Hrs. Labor	at 91		\$	
	Hrs. Labor	at		\$	
2	Hrs. Compressor	at 1.20		\$	2.40
	Compensation Ins.	at \$ 222.6 per C.		\$	41
	Trucking			\$	1.00
	Pav't Patch			\$	14.85
	Tap by Moquin			\$	
	O'head			\$	
				\$	55.62

St. Sanford
 TT. No. 163

Name of Owner Mary Lamoy

Labor and Mat'l. Report Nov. 24 1950

SW corner Sagamore St

● Curb Box

Sanford St.
 6" Main Elev. of Main at tap 5'

Gate at ● Gate at ●

TAX ID # 303.9-13-1

● Curb Box

TAP ON SANFORD ST.
 26' to main
 3/4" copper

LSM-5C 10-21-49