

### Labor and Materials

1	Copper } Connection	3	\$ 3.20
	Lead } .....		
	Curb } Cock		
	Valve } .....		
	T.S. & V. } 3/4 in.		\$ 1.00
1	Service Box { Short 3 1/2 x 4 1/2		
	Old returned { Long 4 1/2 x 5 1/2		
	Buff. or Rdway }		\$ 1.30
8	Ft. 3/4 in. { Copper		
	Galv. Iron } Pipe at		\$ 1.76
	Cast Iron }		
	Nipples..... in. at.....		\$
	Bushings..... to..... in. at.....		\$
	Red'g } Couplings..... to..... in. at.....		\$
	Inc'g }		
	Union..... in. at.....		\$
	Meter..... in. at.....		\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement at.....		\$
	Paving Brick { Mack		
	Red } at.....		\$
	Asphalt }		
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
2	Hrs. Foreman at.....	6 1/2	\$ 1.25
5	Hrs. Common Labor at.....	50	\$ 2.50
5	Hrs. Common Labor at.....	40 1/8	\$ 2.03
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
	Hrs. Compressor at.....		\$
	Compensation Ins.....		\$ 1.15
	Trucking.....		\$ 1.00
	Builders' Use of Water.....		\$
Total \$			14.19

26-18  
6

Labor and Material Report *April 14* 19 *71*

*no 4 Serrella st*

*House 6*

● Curb Box

*HOUSE IS USING TAP TO DAIRY*

*4\"/>
Elev. of Main at tap *6'**

---

Gate at ● TAX ID# 302.12-18-13 ● Gate at

---

*8' to main* ● Curb Box  
*3/4 COPPER*  
*new tap*

*Tap for dairy*

*old 1/2\"/>*

*MAIN 7-1-1971*