

LABOR AND MATERIALS

1	Copper lead	Connection	3/4		\$ 1.23
1	Curb	Cock Valve T. S. & V.	3/4 in.		\$ 1.68
1	Service Box	Short 3 1/2 x 4 1/2			\$ 1.54
	Old returned	Long 4 1/2 x 5 1/2			
28	Ft.	3/4 in.		Pipe at 17	\$ 4.76
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	Couplings	to in. at		\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints	at			\$
	Leadite Joints	at			\$
	Hrs. Foreman	at			\$
3	Hrs. Chauffeur	at	6 1/2		\$ 1.88
8	Hrs. Tapper	at	4		\$ 5.00
8	Hrs. Labor	at	45		\$ 3.60
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$ 32
	Trucking				\$ 1-
	Builders Use of Water	Patch			\$ 5-
	Top 1/4 Penet				\$
					\$
					\$
					\$
					\$
					\$ 26.01

79 -- 1939

St. **15**
 Pl. **15**
 Ave. No. **15**

Sarella

Name of Owner

Fred Lambert

Labor and Mat'l. Report

Sept 25 1939



● Curb Box

4 Main

Elev. of Main at tap **6**

Gate at ●

● Gate at

TAX ID # 302.12-26-2

28' to MAIN
 3/4" COPPER

● Curb Box

old shut off