

LABOR AND MATERIALS

1 Copper ~~head~~ Connection $\frac{3}{4}$ " \$ _____
 1 Curb Cock $\frac{3}{4}$ in. *oviseat* \$ _____
 1 Service box *Short $3\frac{1}{2}$ x $4\frac{1}{2}$* } \$ _____
 Old returned *Buff. or Rdway* }
 28'-10" Ft. $\frac{3}{4}$ in. { Copper } Pipe at \$ _____
 Nipples in. at \$ _____
 Bushings to in. at \$ _____
 Red'g } Coupl'gs to in. at \$ _____
 Inc'g }
 Union in. at \$ _____
 Meter in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman at \$ _____
 Hrs. Labor- at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
TAP BY PURVIS & CO \$ _____
Sept 20-1976 \$ _____
 O'head \$ _____

St. SARELLA Ave. No. 9
 Name of Owner Edith Block
 Labor and Mat'l. Report Sept 20 1976

4" Main Elev. of Main at tap 6'
 Gate at • Gate at •
 TAX ID# 302.12-26-5
 • Curb Box
 28' 10" to main
 3/4" COPPER

LSM-5C-6.1-67