

Labor and Materials

1	Copper	Connection	3/4	\$ 1.25
1	Curb	Cock Valve T.S.&V.	3/4 in	\$ 1.70
1	Service Box	Old returned	Short 6 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	\$ 1.45
11	Ft. 3/4 in.	Copper Galv. Iron Cast Iron	Pipe at	\$ 1.49
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lbs. Br. Stone	at		\$
	Lbs. Sand	at		\$
	Bags Cement	at		\$
	Paving Brick	Mack Red Asphalt at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
7	Hrs. Foreman	at	6.25	\$ 1.25
16	Hrs. Common Labor	at	4.5	\$ 7.20
	Hrs. Common Labor	at		\$
	Hrs. Mason	at		\$
	Hrs. Masons Helper	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins		3.7	\$
	Trucking		1.0	\$
	Builders Use of Water	Patch	5.0	\$

Total \$70.66

1930-79

12

Labor and Material Report July 24

19

3' tap at 10 barrels at



4" Main

Elev. of Main at tap 4'

Gate at TAX ID # 302.12-18-110

Gate at

Curb Box

Old tap shut off at main
(No fine same ditto)

11' to MAIN
3/4" COPPER

118