

Labor and Materials

Copper	} Connection.....	3	1.33	
Lead				
Curb	} Cock	1/4	3/4	
				} Valve
} Service Box	} Short 3 1/2 x 4 1/2		1.36	
				} Old returned
10 Ft.	} Copper	} Pipe at	3	
				} in.
Nipples	in. at			
Bushings	to	in. at		
Red'g	} Couplings.....	to	in. at	
Inc'g				
Union	in. at			
Meter	in. at			
Lbs. Br. Stone	at			
Lbs. Sand	at			
Bags Cement	at			
Paving Brick	} Mack	} at		
				} Red
Lead Joints	at			
Leadite Joints	at			
2 Hrs. Foreman	at		1.25	
Hrs. Common Labor	at			
2 Hrs. Common Labor	at		9.0	
Hrs. Mason	at			
Hrs. Masons Helper	at			
Hrs. Compressor	at			
Compensation Ins			.07	
Trucking			1.00	
Builders Use of Water				

Outside

Total \$ 24.4

33-43 #5

Labor and Material Report

July 6, 1908

Sargent St Lot #5



6 Main Elev. of Main at tap 4.2

Gate at ●

● Gate at

● Curb Box

New House

10' to main
3/4" copper

(4)