

LABOR AND MATERIALS

1	Copper Lead	Connection	1"	\$
1	Curb	Cock Valve T. S. & V.	1 in.	\$
2	Service box	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
	Old returned			
60'	1 1/2 Ft.	Copper G.I. Pipe at		\$
		Nipples	in. at	\$
		Bushings	to in. at	\$
		Red'g Inc'g	Coupl'gs to in. at	\$
		Union	in. at	\$
		Meter	in. at	\$
		Lead Joints	at	\$
		Compound Joints	at	\$
		Maintenance Foreman		\$
		Hrs. Water Maint. Man-1	at	\$
		Hrs. Water Maint. Man-2	at	\$
		Hrs. Garage Foreman	at	\$
		Hrs. Labor	at	\$
		Hrs. Compressor	at	\$
		Compensation Ins.	at \$ per C	\$
		Trucking		\$
		Pav't Patch		\$
		Tap by Miller & Co		\$
				\$
				\$
		O'head		\$
				\$

Shot off For 1" Line
AND
Sargent

St. Pl. Ave. No. 6

Name of Owner
TAX ID # 302.12-6-2

Labor and Mat'l. Report March 1964

