

Labor and Materials

1	Copper	Connection	3/4	\$
	Lead			
1	Curb	Cock Valve	3/4 in.	\$
		T. S. & V.		
	Service Box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		
		Buff. or Rdway		
1/2	Ft.	3/4 in.	Copper Galv. Iron Cast Iron	Pipe at \$
	Nipples	in. at.		\$
	Bushings	to in. at.		\$
	Red'g Inc'g	Couplings	to in. at.	\$
	Union	in. at.		\$
	Meter	in. at.		\$
	Lbs. Br. Stone	at.		\$
	Lbs. Sand	at.		\$
	Bags Cement	at.		\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints	at.		\$
	Leadite Joints	at.		\$
2	Hrs. Foreman	at.		\$
4	Hrs. Common Labor	at.	50	\$
7	Hrs. Common Labor	at.		\$
	Hrs. Mason	at.		\$
	Hrs. Mason's Helper	at.		\$
	Hrs. Compressor	at.		\$
	Compensation Ins.			\$
	Trucking			\$
	Builders' Use of Water			\$
Total \$				\$

27-226 Labor and Material Report *Nov 28* 19 *27*

Box #3 Second St.



6" Main

Elev. of Main at tap 5'

Gate at ●

TAX ID # 309-12-7-29 ● Gate at

● Curb Box

old saw gap shut
6/6

11' to MAIN
3/4" copper