Labor and Materials

COPPER

1	Lead Connection 3/4	$
1	Curb Cock 3/4	$
1	Service Box Old returned { Short 3½ x 4½ / ~~Long 4½ x 6½~~ / Buffalo }	$
12	Ft. 3/4 in. G. I. Pipe at COPPER	$
	Nipples in. at	$
1	Bushings 3/4 to 1/2 in. at	$
	Red'g Coup to in. at	$
	Inc'g Coup to in. at	$
	Union in. at	$
	Meter in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
3	Hrs. Foreman at	$
7	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. at	$
	Hrs. at	$
Inc	Builders' Use of Water	$
	at	$
Truck 1.00	at	$
	at	$
	at	$
	Total	$ 12.68

June

Labor and Material Report 11 1925

25 Second St

6 Main

Elev. of Main at tap 4½

Gate at ● ● Gate at

TAX ID # 309.12-7-28

● Curb Box

12' to MAIN

3/4" COPPER