

Labor and Materials

1	Copper	} Connection	3/4	\$.50
1	Lead				
1	Curb	} Cock Valve T.S.&V.	} 3/4 in	\$.70
1	Service Box				
1	Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway	}	\$.50
23	Ft. 3/4 in.				
		} Copper Galv. Iron Cast Iron	} Pipe at	\$.37
	Nipples				
	Bushingsto.....in. at.....			
	Red'g Inc'g	} Couplingsto.....in. at.....	
	Union				
	Meterin. at.....			
	Lbs. Br. Stone	at.....			
	Lbs. Sand	at.....			
	Bags Cement	at.....			
	Paving Brick	} Mack Red Asphalt	} at.....	
	Lead Joints				
	Leadite Joints	at.....			
3	Hrs. Foreman	at.....	6 1/2		\$.88
16	Hrs. Common Labor	at.....	45		\$.70
	Hrs. Common Labor	at.....			
	Hrs. Mason	at.....			
	Hrs. Masons Helper	at.....			
	Hrs. Compressor	at.....			
	Compensation Ins			\$.24
	Trucking			\$.17
	Builders Use of Water			

Total \$ 19.43

119 34

Labor and Material Report Sept 22 1930

26 Second St



6" Main

Elev. of Main at tap 5 1/2

Gate at TAX ID # 309.12-10-18 Gate at

Curb Box

old shut off at gate
23' to MAIN
3/4" COPPER

John F. Reardon