

### Labor and Materials

1	Copper } Connection $\frac{3}{4}$ "	\$ 3.20
1	Lead } Connection $\frac{3}{4}$ "	\$ 1.00
1	Curb { Cock Valve T.S. & V. } 2" in.	\$ 1.00
1	Service Box { Short 3" x 4" Long 4" x 5" Buff. or Rdway }	\$ 1.40
10	Ft. $\frac{3}{4}$ " in. { Copper Galv. Iron Cast Iron } Pipe at	\$ 2.28
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g } Couplings..... to..... in. at.....	\$
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack Red Asphalt } at.....	\$
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
2	Hrs. Foreman at..... 6.25-	\$ 12.50
17	Hrs. Common Labor at..... 5.0	\$ 3.50
	Hrs. Common Labor at.....	\$
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 1.13
yes	Trucking.....	\$ 1.00
NO	Builders' Use of Water.....	\$
	<b>Total</b> \$	<b>13.68</b>

27-13

Labor and Material Report

April 14 1927

No 29 Second St



6" Main

Elev. of Main at tap

51

Gate at

TAX ID # 309.12-7-26

Gate at

Curb Box

Old Tap shut off,  
10' to MAIN  
 $\frac{3}{4}$ " COPPER