

Labor and Materials

.....	Copper	}	Connection.....	\$.....	
.....	Lead				
.....	Curb	}	Cock Valve T. S. & V.in.....	\$.....	
.....	Service Box				
.....	Old returned	}	Short 3½ x 4½	\$.....	
			Long 4½ x 5½		
			Buff. or Rdway		
.....	Ft.in.	}	Copper	Pipe at.....	
			Galv Iron		
			Cast Iron		
.....	Nipplesin. at.....		\$.....	
.....	Bushingsto.....in. at.....		\$.....	
.....	Red'g	}	Conplings.....to.....in. at.....	\$.....	
.....	Inc'g				
.....	Unionin. at.....		\$.....	
.....	Meterin. at.....		\$.....	
.....	Lead Joints	at.....		\$.....	
.....	Leadite Joints	at.....		\$.....	
.....	Hrs. Foreman	at.....		\$.....	
.....	Hrs. Chauffeur	at.....		\$.....	
.....	Hrs. Tapper	at.....		\$.....	
.....	Hrs. Labor	at.....		\$.....	
.....	Hrs. Labor	at.....		\$.....	
.....	Hrs. Compressor	at.....		\$.....	
.....	Compensation Ins.		\$.....	
.....	Trucking		\$.....	
.....	Builders Use of Water		\$.....	
.....				\$.....	
.....				\$.....	
.....				\$.....	
.....				\$.....	
.....				\$.....	
.....				\$.....	

St.
 Pt.
 Ave. No. 31

Second

Name of Owner
Hart TAX ID # 309.12-7-25

Labor and Mat'l. Report 11-22 1918

6" Main Elev. of Main at tap.....

Gate at ● ● Gate at

● Curb Box