

### Labor and Materials

1	Copper } Connection	3	\$ 3.20
1	Curb { Cock Valve T. S. & V. }	1	\$ 1.00
1	Service Box { Short 3 1/2 x 4 1/2 Old returned { Long 4 1/2 x 5 1/2 Bull. or Rdway }		\$ 1.20
20	Pt. in. { Copper Galv. Iron Cast Iron }	3/4	\$ 4.00
	Nipples..... in. at.....		\$
	Bushings..... to..... in. at.....		\$
	Red'g } Couplings..... to..... in. at.....		\$
	Union..... in. at.....		\$
	Meter..... in. at.....		\$
	Lbs. Br. Stone at.....		\$
	Lbs. Sand at.....		\$
	Bags Cement at.....		\$
	Paving Brick { Mack Red Asphalt }		\$
	Lead Joints at.....		\$
	Leadite Joints at.....		\$
3	Hrs. Foreman at.....	5.25	\$ 1.88
16	Hrs. Common Labor at.....	20.75	\$ 6.20
	Hrs. Common Labor at.....		\$
	Hrs. Mason at.....		\$
	Hrs. Mason's Helper at.....		\$
	Hrs. Compressor at.....		\$
	Compensation Ins.....		\$ 2.20
	Trucking.....		\$ 10.00
	Builders' Use of Water.....		\$
Total			\$ 19.50

28-77

Labor and Material Report July 16 1929

4 Second St

TAX ID# 309.12-10-7

6 Main Elev. of Main at tap 5

Gate at ● Gate at ●

● Curb Box

20' to MAIN  
3/4" COPPER  
old tap shut off