

LABOR AND MATERIALS

| | | | | |
|----|-------------------------|------------------------------------------------------------------------------|------------------|------------|
| 1 | Copper | Connection | 3/4" | \$ |
| 1 | Curb | Cock Valve | 3/4 in. orise #1 | \$ |
| 1 | Service box | { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Relay. } | | \$ |
| | Old returned | | | |
| 23 | Ft. | Copper | 3/4 in. | Pipe at \$ |
| | Nipples | in. | at | \$ |
| | Bushings | to | in. | at \$ |
| | Red'g | } Coupl'gs | to | in. |
| | Inc'g | | | |
| | Union | in. | at | \$ |
| | Meter | in. | at | \$ |
| | Lead Joints | at | | \$ |
| | Compound Joints | at | | \$ |
| | Maintenance Foreman | | | \$ |
| | Hrs. Water Maint. Man-1 | at | | \$ |
| | Hrs. Water Maint. Man-2 | at | | \$ |
| | Hrs. Garage Foreman | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Compressor | at | | \$ |
| | Compensation Ins. | at \$ | per C | \$ |
| | Trucking | | | \$ |
| | Pav't Patch | | | \$ |
| | Tap Made By Bifford Co | | | |
| | April-17-1975 | | | |
| | O'head | | | \$ |

↓

St. No. 5

Second

Name of Owner Richard Mingo

Labor and Mat'l. Report April 17 1975

4" Main Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID # 309.12-8-19

● Curb Box

TAP ON JUVET ST

23' to main

3/4" COPPER

LSM-56-6-1-67