

Labor and Materials

Copper	}	Connection.....			\$		
Lead							
Curb	}	Cock Valve T. S. & V. } in		\$		
Service Box				}	Short 3½ x 4½ Long 4½ x 5½ Buff. or Rdway		\$
Old returned							
22 Ft. 3/4 in.	}	Copper Galv Iron Cast Iron	Pipe at			\$	
Nipples	 in. at			\$		
Bushings		to	in. at		\$		
Red's Inc's	}	Conplings.....	to	in. at	\$		
Union				 in. at		\$
Meter	 in. at			\$		
Lead Joints at					\$		
Leadite Joints at					\$		
Hrs. Foreman at					\$		
Hrs. Chauffeur at					\$		
Hrs. Tapper at					\$		
Hrs. Labor at					\$		
Hrs. Labor at					\$		
Hrs. Compressor at					\$		
Compensation Ins.					\$		
Trucking					\$		
Builders Use of Water					\$		
					\$		
					\$		
					\$		
					\$		
					\$		
					\$		

St. _____
 Pl. _____
 Ave. No. 10

2nd

Name of Owner _____

Labor and Mat'l. Report 1920

3 1/4" - 26 3"

● Curb Box

TAX ID # 309.12-10-10

.....Main

Elev. of
Main at tap.....

Gate at ● ● Gate at

● Curb Box

22' to MAIN

3/4" GAL.