

Labor and Materials

Copper } Connection.....	\$ 96
Lead }	
Curb { Cock }	\$ 1.33
{ Valve }	
{ T. Box }	
Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.35
Old returned { Long 4 1/2 x 5 1/2 }	
{ Buff. or R. Way }	
9 Ft. in. { Copper } Pipe at 15¢	\$ 1.35
{ Galv. Iron }	
{ Cast Iron }	
Nipples in. at	\$
Bushings to in. at	\$
Red'g } Couplings..... to in. at	\$
Inc'g }	
Union..... in. at	\$
Meter..... in. at	\$
Lbs. Br. Stone at	\$
Lbs. Sand at	\$
Bags Cement at	\$
Paving Brick { Mack } at	\$
{ Red }	
{ Asphalt }	
Lead Joints at	\$
Leadite Joints at	\$
Hrs. Foreman at	\$
Hrs. Common Labor at	\$
Hrs. Common Labor at	\$
Hrs. Mason at	\$
Hrs. Masons Helper at	\$
Hrs. Compressor at	\$
Compensation Ins	\$
Trucking	\$
Builders Use of Water <i>no patch BP</i>	\$
Total \$	

04/26
Labor and Material Report

June 4 1936

27 Sheridan St



6 Main

Elev of Main at tap 4 1/2

Gate at ● TAX ID # 302.19- ● Gate at
3/4 COPPER 5-15

9' to MAIN ● Curb Box

old sheet off a (main)

Taylor
(to be charged)

Handwritten initials