

**Labor and Materials**

4	Copper	Connection	3/4"	\$	96
4	Lead	Cock		\$	133
4	Curb	Valve	3/4"	\$	135
1	Service Box	Short 3 1/2 x 4 1/2		\$	135
	Old returned	Long 4 1/2 x 5 1/2		\$	
8	Ft.	Copper	15	\$	120
		Galv. Iron		\$	
		Cast Iron		\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Couplings	to in. at	\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lbs. Br. Stone	at		\$	
	Lbs. Sand	at		\$	
	Bags Cement	at		\$	
	Paving Brick	Mack	at	\$	
		Red		\$	
		Asphalt		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
	Hrs. Foreman	at		\$	
	Hrs. Common Labor	at		\$	
	Hrs. Mason	at		\$	
	Hrs. Masons Helper	at		\$	
	Hrs. Compressor	at		\$	
	Compensation Ins			\$	
	Trucking			\$	
	Builders Use of Water			\$	
	<b>Total \$</b>				

Labor and Material Report

June 5 1936  
33 Sheridan St



6 Main

Elev of Main at tap 4 1/2

Gate at

TAX ID # 302.14-5-13

Gate at

● Curb Box

old shut off at main  
Robertson  
(take charged)

8' to main

3/4" Copper