Labor and Materials

1	~~Lead~~ Connection	$
1	Curb Cock 3/4	$
1	Service Box ~~Old returned~~ { Short 3½ x 4½ / ~~Long 4½~~ x 5½ / Buffalo	$
12	Ft. 3/4 in. G. I. Pipe at	$
	Nipples ..... in. at	$
	Bushings ..... to ..... in. at	$
	Red'g Coup .... to .... in. at	$
	Inc'g Coup .... to .... in. at	$
	Union .... in. at	$
	Meter .... in. at	$
	Cu. Yds. Br. Stone at	$
	Cu. Yds. Sand at	$
	Bags Cement at	$
	Paving Brick { Mack / Red / Asphalt } at	$
2	Hrs. Foreman at	$
8	Hrs. Common Labor at	$
	Hrs. Mason at	$
	Hrs. ..... at	$
	Hrs. ..... at	$
4½	Builders' Use of Water	$
	..... at	$
	Truck ..... at	$
	..... at	$
	..... at	$
	Total	$

Labor and Material Report July 3 19 25

#66

Tap Sheridan St Left Side from Garfield Ld

Robinson

6" Main

Elev. of Main at tap 4½

Gate at ● ● Gate at

TAX ID # 302.19-83

● Curb Box

12' to MAIN

3/4" GAL.