

LABOR AND MATERIALS

Copper	}	Connection	\$
Lead			
Curb	}	Cock	in. \$
		Valve	
		T. S. & V.	
Service box Old returned	}	Short 3½X4½	\$
		Long 4½X5½	
		Buff or Rdway	
Ft. in.	}	Copper	Pipe at \$
		G. I.	
		C. I.	
Nipples	in. at	\$	
Bushings	to in. at	\$	
Red'g Inc'g	}	Coupl'gs	to in. at \$
Union	in. at	\$	
Meter	in. at	\$	
Lead Joints	at	\$	
Compound Joints	at	\$	
Hrs. Water Maint. Man-1	at	\$	
Hrs. Water Maint. Man-2	at	\$	
Hrs. Labor	at	\$	
Hrs. Labor	at	\$	
Hrs. Compressor	at	\$	
Compensation Ins.	at \$ per C	\$	
Trucking		\$	
Pav't Patch		\$	
O'head		\$	
		\$	

Sheridan

St.
Pl. Ave. No. 74

Name of Owner _____

Labor and Mat'l. Report

Nov 4

1953

38'1" 41'2"

● Curb Box

6"

● Main

Elev. of
Main at tap 5'

● Gate at

● Gate at

TAX ID # 302.19-8-7

● Curb Box

LSM-5C 5 15-48