

LABOR AND MATERIALS

1	Copper Lead	{ Connection	3/4"		\$ 2.29
1	Curb	{ Cock Valve T.S. & V.	3/4" in.		\$ 2.70
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway			\$ 4.25
2.5	Ft.	{ Copper C.I. C.I.	3/4 in.	Pipe at 35	\$ 7.35
	Nipples	in. at			\$
	Bushings	to in. at			\$
	Red'g Inc'g	{ Coupl'gs to in. at			\$
	Union	in. at			\$
	Meter	in. at			\$
	Lead Joints at				\$
	Compound Joints at				\$
1 1/2	Hrs. Water Maint. Man-1	at	1.12		\$ 5.67
3	Hrs. Water Maint. Man-2	at	1.02		\$ 3.06
18	Hrs. Labor	at	91		\$ 6.38
	Hrs. Labor	at			\$
1	Hrs. Compressor at		1.20		\$ 1.20
	Compensation Ins. at	\$ 2.226 per C.			\$ 4.5
	Trucking				\$ 10.80
	Pay't Patch				\$
	Tap by Moquin				\$
	O'head				\$
					\$ 50.04

12-19-50

✓

Sheridan

St. No. 93
Pl. Ave. No. 93

Name of Owner Knapp. 95

Labor and Mat'l. Report July 10 19 50

#93

43' 45'

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

TAX ID# 302.19-3-7

21' to main
3/4" copper ● Curb Box