

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead				
Curb	} Cock	} in.	\$	
				} Valve
Service box	} Short 3½ x 4½	}	\$	
				} Long 4½ x 5½
Old returned				
Ft.	} Copper	} Pipe at	\$	
				} G. I.
in.				
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g	} Coupl'gs	} to in. at	\$	
				Inc'g
Union	in. at		\$	
Meter	in. at		\$	
Lead Joints	at		\$	
Compound Joints	at		\$	
Maintenance Foreman			\$	
Hrs. Water Maint. Man-1	at		\$	
Hrs. Water Maint. Man-2	at		\$	
Hrs. Garage Foreman	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins. at \$	per C		\$	
Trucking			\$	
Pav't Patch			\$	
			\$	
			\$	
			\$	
O'head			\$	
			\$	

4. Sherman Ave.
Was

St. No. 368
Pl. Ave. No. 368

Name of Owner
Ernst House, Cobb.

Measured in
Labor and Mat'l. Report - March 28 1962

6" Sherman Ave. Elev. of Main at tap

Gate at • To be razed • Gate at
shut off at curb.

● Curb Box

Buffalo box
This Curb box shut off
Gas Station at 366 Glen

LSM-SC-8-10-61