

### Labor and Materials

1	Lead Connection	3/4"	\$
1	Curb Cock	1"	\$
1	Service Box	(Short 3 1/2 x 4 1/2)	\$
1	Old returned	(Long 4 1/2 x 5 1/2)	\$
6	Ft. 1"	in. G. I. Pipe at	\$
	Nipples	in. at	\$
	Bushings	in. at	\$
	Red'g Coup	to in. at	\$
	Inc'g Coup	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
	Cu. Yds. Br. Stone	at	\$
	Cu. Yds. Sand	at	\$
	Bags Cement	at	\$
	Pav. Brick	{ Mack Red Asphalt } at	\$
3	Hrs. Foreman	at	\$
9	Hrs. Com. Labor	at	\$
	Hrs. Mason	at	\$
	Hrs.	at	\$
	Hrs.	at	\$
	Builders' Use of Water	at	\$
	Trucks	100 at	\$
		at	\$
		at	\$
		at	\$
	Total	\$	12.33

### Labor and Material Report

Aug 14 1923

36" tap at 18 + 18 1/2 Sherman Ave



6" Main

Elev. of Main at tap

5'

Gate at ●

● Gate at

TAX ID# 302.20-21-7

● Curb Box

6' to main  
1" GAL.