

Labor and Materials

1	Copper } Connection.....	\$ 3.20
	Lead	
1	Curb { Cock } 3/4 in.....	\$ 1.00
	Valve	
	T. S. & V.	
1	Service Box { Short 3 1/2 x 4 1/2 }.....	\$ 1.20
	Old returned { Long 4 1/2 x 5 1/2 } Buff. or Rdway	
14	Ft. 3/4 in. { Copper } Pipe at.....	\$ 3.08
	{ Galv. Iron }	
	{ Cast Iron }	
	Nipples..... in. at.....	\$
	Bushings..... to..... in. at.....	\$
	Red'g } Couplings..... to..... in. at.....	\$
	Inc'g }	
	Union..... in. at.....	\$
	Meter..... in. at.....	\$
	Lbs. Br. Stone at.....	\$
	Lbs. Sand at.....	\$
	Bags Cement at.....	\$
	Paving Brick { Mack } at.....	\$
	{ Red }	
	{ Asphalt }	
	Lead Joints at.....	\$
	Leadite Joints at.....	\$
3	Hrs. Foreman at... 62.5	\$ 1.88
	Hrs. Common Labor at.....	\$
14	Hrs. Common Labor at... 40 1/2	\$ 56.9
	Hrs. Mason at.....	\$
	Hrs. Mason's Helper at.....	\$
	Hrs. Compressor at.....	\$
	Compensation Ins.....	\$ 94
	Trucking.....	\$ 1.00
	Builders' Use of Water.....	\$
Total \$		173.6

26-140
Labor and Material Report

19 26

3 Tap 136 Shuman Ave



6" Main

Elev. of Main at tap

Gate at

TAX ID # 309.7-4-4

Gate at

Curb Box

14' to main
3/4" copper