

Labor and Materials

1	Copper } Connection.....	\$ 2.60
	Lead }	
1	Curb } Cock }	\$ 2.27
	Valve }	
	P. S. & V. }	
1	Service Box } Short 3 1/2 x 4 1/2 }	\$ 1.38
	Old returned } Long 4 1/2 x 5 1/2 }	
		Buff. or Rdway }
24	Ft. in. } Copper } Pipe at	\$ 4.32
		Galv. Iron }
		Cast Iron }
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g } Couplings to in. at	\$
	Inc'g }	
	Union in. at	\$
	Meter in. at	\$
	Lbs. Br. Stone at	\$
	Lbs. Sand at	\$
	Bags Cement 'at	\$
	Paving Brick } Mack } at	\$
		Red }
		Asphalt }
	Lead Joints at	\$
	Leadite Joints at	\$
34	Hrs. Foreman at	\$ 47
2	Hrs. Common Labor at Tapper	\$ 1.-
16	Hrs. Common Labor at	\$ 7.20
	Hrs Mason at	\$
	Hrs Mason's Helper at	\$
	Hrs. Compressor at	\$
	Compensation Ins	\$.76
	Trucking	\$ 1.-
	Builders' Use of Water	\$
Total \$		70.50

Labor and Material Report 4-21-1931

137 Sherman Ave.

No measurement.

● Curb Box

6 Main

Elev of Main at tap 5-

Gate at ●

● Gate at

● Curb Box

24' to main

3/4" copper